

FOREST LOOKOUTS

[OREGON](#)[BAKER COUNTY](#)[BENTON COUNTY](#)[CLACKAMAS COUNTY](#)[CLATSOP COUNTY](#)[MORE...](#)[LINCOLN COUNTY](#)

SADDLEBAG MOUNTAIN

Oregon Department of Forestry - Lincoln FPA
6S-9W-35

1952: "Saddle Bag and Rocky Top were on a part-time schedule, when visibility was poor." (**Lincoln FPA Annual Report**)

1953: "Construction of a 40 foot high cedar pole tower with 10 x 10 cabin and a 3 foot catwalk in Sec. 36 T^S R(W, overlooking Salmon River District. The cost of material, \$252.74; and cost of labor, \$927.48; Total cost of \$1180.22. 100% of the work is done." (**Lincoln FPA Annual Report**)

1954: Lightning arrestor installed on Saddle Bag. (**Lincoln FPA Annual Report**)

1955: "Painting was done in the Saddle Bag Lookout cabin." (**Lincoln FPA Annual Report**)

1956: "Made and placed shutters on Saddle Bag Lookout tower." (**Lincoln FPA Annual Report**)

1959: "At Saddle Bag Lookout, the roof and shutters were repaired; galvanized steel sheet material was put under the windows and the cabin was painted on the outside." (**Lincoln FPA Annual Report**)

1960: "Repair of the roof and shutters on the Saddle Bag Lookout tower." (**Lincoln FPA - Annual Report**)

1964: The cab on the tower was replaced at a cost of \$1019.55.



1969: The lookout was dismantled after several years of not being used. Between wind damage and vandalism repairs were too expensive.

REX'S FIRE LOOKOUT PAGE



MEMBER: FOREST FIRE LOOKOUT
ASSOCIATION

